

Ø813Z 23 JAN 63

S E C R E T

TO : DIRECTOR 25X1A

FROM : [REDACTED]

SUBJECT: OSA (1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16)

PRIORITY

INFO: S/C (17)

TOR 1Ø35Z 23 JAN 63

25X1A

25X1A

25X1A

IN 63487

25X1A

PRITY [REDACTED]

INFO

REF

[REDACTED] Ø666

[REDACTED] COMMO OPERA LOGS

25X1A REF [REDACTED] Ø649

25X1A

MALFUNCTION REPORT [REDACTED] 3Ø

1. MISSION 3215. "Q" BAY PRESSURE FAILING CAUSED HIGH VOLTAGE ARCING IN POWER/SUPPLY. BLOWING TWO POWER TRANSISTORS TYPE 2N174. UNITS REPLACED AND BENCH CHECKED OK.

2. AIRCRAFT CHECK INDICATES [REDACTED] 3Ø OPERATIONAL.

END OF MESSAGE

25X1A

S E C R E T

GROUP 1  
Excluded from automatic  
downgrading and  
declassification